

Bosch LSU4.9 Wideband Sensor



Sensor Pin	Output	ECU Pin Type
Pin 1	Pump Current	LSU IP
Pin 2	Virtual Ground	LSU VM
Pin 3	Heater Voltage H-	LSU Heater -ve
Pin 4	Heater Voltage H+	LSU Heater +ve
Pin 5	Trim Resistor	LSU IA
Pin 6	Nernst Voltage	LSU UN

